# BobCAD-CAM Training Seminar

BobCAD-CAM is having a professional Training Seminar near you!

Date: March 19, 20, 21, 2014 Training Seminar Location: Rochdale, UK



N12766 X2.8867 Y.5567 Z-.1315 N12767 X2.888 Y.5521 Z-.1258 N12768 X2.8939 Y.5299 Z-.102

## BobCAD-CAM

Where: Office 3 Evans Business Centre Dante St Rochdale, OL12 6XB

Phone: 01706-861717 (Office) 07775-860661 (Cell)

Hotel Price: Call Peter for instructions: TEL:01706 861717

Shuttle: Call Peter for instructions: TEL:01706 861717

### **Class Details**

#### Training Subject: BobCAD-CAM

#### **Class Materials:**

A laptop is not required for the seminar but is recommended to practice at night. If you have questions, you can ask your trainer the following day.

#### Class Times:

Days 1 & 2 (Wed & Thurs): 8:30am - 5:30pm Day 3 (Fri): 8:30am-5:30pm - May end early due to completion

#### **Certification:**

Professional BobCAD-CAM Software Operator

#### **Optional:**

Evening training is on additional software such as BobART and Lathe (Call for price and to sign-up.) Times: 6:30pm - until completed

N12766 X2.8867 Y.5567 Z-.1315 N12767 X2.888 Y.5521 Z-.1258 N12768 X2.8939 Y.5299 Z-.102

(Note: The actual seminar may differ from the outlined agenda below.)

(Note: The actual seminar may differ from	Day 2	Day 3	
-Introduction	-2D CAD	-CAM Settings	
-Interface Overview		Adding Toolo	
	-Dimensions	-Adding Tools	
-Menus & Toolbars	-The UCS Introduction	-Feed Rates & Materials	
-Layer Post Manager	-Contours	-Post Processor Selection and Installation	
-Software Settings and Preferences	-contours		
-Customizing the Interface & Toolbars	-Basic 2D Drawings	-What is a Post Processor?	
-Shortcuts	-Part Example Wagon Wheel Example	-How to Select & Install a Post Processor	
-File Importations	-CAM Overview and CAM Tree Explanation -Machine File Setup		
-File Open / Import Types			
-File Open vs. Merge	-CAM Tree Overview	-CAD 3D Drawing	
-Basic CAD Features	-Tool Patterns	-3D Introduction – Solids	
-Points, Lines, Arc, Other	-Settings Default	-Boolean Functions Gear Box	
-Offsets	-Operations Templates	-Extracting Edges Gear Box	
-Translate, Rotate, Mirror			
-Trim & Break	-Part Orientation	-Using the Stich & Unstitch Functions	
-Layers & Colors	-The Stock Wizard	-Part File Grip Cavity	
-Selection Methods	-Basic Toolpath	-Surfaces Introduction	
-Selection Mode	-2D Toolpath Wizards	-Surface Tools	
-Chain Selection			
-Window Selection	-CAM	-Importing & Repairing	
-Color & Layer Selection	-Toolpaths & Simulation	-3D Toolpaths	
-Hole Patterns / Point Patterns	-Questions & Answers	-3D Toolpath Overview	
-Questions & Answers		-3D Toolpath Examples	
Additional Evening Training	Additional Evening Training		
Evening 1 - BobART	Evening 2 - Lathe	-Questions & Answers	
-	~		

Please fill out the information below and fax back to	727-450-6446 to comple	ete your reservation.	
Name:			
Company:			
Mailing Address:			
City: Sta	ate: Zip	D:	
Phone: Fa	ax:		
Seminar dates and location: Rochdale, UK - March 21-23,	2014		
Cost is \$599 British Sterling Pounds per person for 3 - Day	/s (group discounts also ava	ilable, call for pricing).	
Evening Training on BobART or Lathe is \$85 British Sterlin	g Pounds per class, per eve	ening - Recommended	
How many people will be attending?	_		
Please print clearly below as we use this for printing certific	cation certificates!		
Who is attending	(Optional - Additional Charge)		
Print Name:	_ BobART Training	Lathe Training	
Print Name:	_ BobART Training	Lathe Training	
Print Name:	_ BobART Training	Lathe Training	
Print Name:	_ BobART Training	Lathe Training	
Method of payment: Credit Fax Check			
Check one: 🔲 VISA 🔲 🔤 🖉	AMERICAN EXPRESS	echeck	
Credit Card # (15 - 16 digits):			
Exp. Date: / CVC Security Code (3 or 4 di	gits)		
Card holders signature:			
Please print your name:			

Fax this registration form to 727-450-6446

For further information please call 877-262-2231 x127 to speak with our Training Coordinator.